

New Light Curtain and Adjustment Delay

TIP Z038-0001

Stacker

Benefits:

• This improvement provides better safety for carton stackers while managing the jogger tools adjustments.

Safety
Obsolescence
Quality
Cost Reduction
Performance
Maintenance



Revised Design Original Design

New Light Curtain Adjustment Delay

Machine Model for Improvement: All Stackers with light Curtains

Description of Improvement:

This improvement provides a set of light curtains to the carton stacker that allows for safer operating conditions during setup. When the operator triggers the light curtains, certain hazarous stacker functions are frozen through safety logic to allow manual tooling adjustments while maintaining operator safety. Once the operator has completed their setup adjustments, the light curtain is reset and normal stacker functionality is enabled.



New Light Curtain Adjustment Delay

Included in this TIP:

- All required parts
- Necessary engineering
- Updated documentation pages for relevant sections

Estimated downtime, no production:

• 3 days

Estimated startup, limited production:

• 1 day

Estimated monitoring in production:

• 1 day

Required manpower:

- 1 BW Papersystems Mechanical Field Service Engineer
- 1 BW Papersystems Electrical Engineer

(Additional local resources to be determined, if needed)

How can we help you? Please do not hesitate to contact us for any questions regarding our comprehensive Customer Service offerings:

TIPs/Upgrades:

tips.zerand@bwpapersystems.com

Spare Parts:

zerandparts@bwpapersystems.com

Service Requests:

• zerandservice@bwpapersystems.com

In case of emergency please contact our hotline 24 hours a day:

NORTH AMERICA +1 262 827 3800

Please note: these statements are for general information only and are subject to change without prior notice. We would be pleased to send you a detailed offer, following an inspection of your machine.

